


# MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 18, Township 10 North, Range 1 West,

Monument Description & Remarks: 5/8" Rebar 0.1' Above Ground 0.8' West of Pavement




COMPLETED By Sh. O. Fawkes

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

*Ben E. Bledsoe*

Indiana Registered Land Surveyor No. S0559



**MONUMENT RECORD**  
**State of Indiana - County of Monroe**

**Section: 18**


**Township: 10 North**

**Range: 1 West**

**Corner ID: Wash A-11**

**Monument Description & Remarks:** Found 5/8" Rebar, bent towards the south, at West edge of Mt. Pleasant Road, at West 1/4 corner of section. Barn nail spike with 1/2" head found at north base of rebar, 3" under gravel.

**References on file in the County Surveyor's Office:** Referenced by Mike Mundy, R.L.S.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 15th day of January, 1998.

*Kevin P. Enright*

Administered by: Surveyor Review Board

